

TOYOTA COROLLA/MATRIX 2009 - DOOR SILL ENHANCEMENT
Preparation

Part Number: PT922-02080-01 (Corolla – Gray)
PT922-02080-11 (Corolla – Dark Gray)
PT922-02080-04 (Corolla – Beige)
PT922-12080-11 (Matrix – Dark Gray)

NOTE: Part number of this accessory may not be the same as the part number shown.

Kit Contents

Item #	Quantity Reqd.	Description
1	1	Front Part - Right Hand
2	1	Front Part - Left Hand
3	1	Rear Part - Right Hand
4	1	Rear Part - Left Hand






Vehicle Service Parts (may be required for reassembly)

Item #	Quantity Reqd.	Description
1	N/A	
2		
3		

Hardware Bag Contents

Item #	Quantity Reqd.	Description
1	N/A	
2		
3		

Legend

	STOP: Damage to the vehicle may occur. Do not proceed until process has been complied with.
	OPERATOR SAFETY: Use caution to avoid risk of injury.
	CAUTION: A process that must be carefully observed in order to reduce the risk of damage to the accessory/vehicle and to ensure a quality installation.
	TOOLS & EQUIPMENT: Used in Figures calls out the specific tools and equipment recommended for this process.
	REVISION MARK: This mark highlights a change in installation with respect to previous issue.

Additional Items Required For Installation

Item #	Quantity Reqd.	Description
1	N/A	
2		
3		

Conflicts

XRS models do not apply

Recommended Tools

Personal & Vehicle Protection	Notes
N/A	
Special Tools	Notes
Nylon Removal Tool	
Installation Tools	Notes
N/A	
Special Chemicals	Notes
N/A	

General Applicability

All 2009 MY Vehicles except XRS models

Recommended Sequence of Application

Item #	Accessory
1	
2	
3	

*Mandatory

Care must be taken when installing this accessory to ensure damage does not occur to the vehicle. The installation of this accessory should follow approved guidelines to ensure a quality installation.

These guidelines can be found in the "Accessory Installation Practices" document.


This document covers such items as:-

- Vehicle Protection (use of covers and blankets, cleaning chemicals, etc.).
- Safety (eye protection, rechecking torque procedure, etc.).
- Vehicle Disassembly/Reassembly (panel removal, part storage, etc.).
- Electrical Component Disassembly/Reassembly (battery disconnection, connector removal, etc.).

Please see your Toyota dealer for a copy of this document.


**1. FRONT DOOR SCUFF PLATE (FR)
REMOVAL**




- (a) Loosen weather strip up to the reference line.
 Gently lift the edges of the scuff plate.
(Fig. 1)

- (b) Slowly remove the scuff plate making sure all three clips are detached from the door trim. (Fig.2)

**2. REAR DOOR SCUFF PLATE (RR)
REMOVAL**






-  (a) Gently lift the flat section (1) then caved portion (2) to detach all clips. Rotate the part towards inside of the car to dislodge small clips at the back. (Fig. 3)

- (b) Carefully remove the scuff plate making sure all clips are detached. (Fig. 4)

NOTE: To avoid damage to mating trim panels, make sure to loosen small clip at the back before removing the rear scuff plate.





3. FRONT DOOR SILL ENHANCEMENT (FR) INSTALLATION

- ⚠ (a) Check Part Number label which indicate specific installation side, Right Hand (RH) or Left Hand (LH).
- ⚠ (b) Align the 3 clips of the parts on insertion holes of the body panel. Make sure the part is clear off the weather strip. (Fig. 5)
- (c) Gently push the door sill enhancement down to insert the clips. (Fig. 6)
- (d) Check for gaps around the edge of the door sill enhancement. Mount the weather strip back. (Fig. 7)

4. REAR DOOR SILL ENHANCEMENT (RR) INSTALLATION

- ⚠ (a) Check Part Number label which indicate specific installation side, Right Hand (RH) or Left Hand (LH).
- (b) Align clip of B-Pillar Edge and push gently to insert clips. Make sure small clip at the C-Side is secured. (Fig. 8)
- (c) Align clip of opposite edge and push gently to insert clips. Make sure small clip at the C-Side is fastened. (Fig. 9)
- (d) Clips on Metal portion will automatically be aligned when preceding steps are properly followed. Push the metal plate down gently to insert the clips. (Fig. 10)
- (e) Check for gaps around the edge of the door sill enhancement. (Fig. 11)

TOYOTA COROLLA/MATRIX 2009 - DOOR SILL ENHANCEMENT
Checklist - these points **MUST** be checked to ensure a quality installation.

Check:

Accessory Function Checks

- Gaps on edges
- Improper fitment

Look For:

All clips must be inserted properly
Remove part and follow installation
procedure accordingly